DIR-820L Firmware Release Notes

Firmware: FW2.02.B04 (Release)
Hardware: B1
Date: 2014/12/02

Note:
FW is not backwards compatible with Ax hardware.

Problems Resolved:
1. Fix mydlink shareport upload issue.

Enhancements:
1. Update mydlink agent.
2. Update Open SSL version.
3. Applying new UNII of FCC.

Known Issues:
None