DIR-850L Firmware Patch Notes

Firmware: 1.21B07_i9d9_WW
Hardware: Ax
Date: October 6, 2018

Note:
If you are currently running firmware version 1.14 or lower, you must update your router to firmware versions 1.15B04 and 1.20B03 first before updating this firmware. Both are available in the 1.21B06 package.

Problems Resolved:

CVE-2018-18907 – Authentication bypass vulnerability.