DIR-850L Firmware Release Notes

Firmware: FW v2.10WWb03
Hardware: Rev. Bx
Release Date: 2017/9/19

Note:

1. The firmware v2.10 is the transitional version for upgrading to v2.20b03 or later version.
2. Below is the procedure for firmware upgrade:
   - Connect to the router via LAN port or WIRELESS interface.
   - Log in to the D-Link management page (http://192.168.0.1 or http://dlinkrouter.local./)
   - Go to the firmware upgrade page, upload the firmware v2.10 and wait for the device to reboot.
   - Log in to the D-Link management page again.
   - Go to the firmware upgrade page and check the button of online firmware version check and the router will download the firmware v2.20b03 and upgrade automatically.
   - Wait for the device to reboot and don't power off the router during the firmware upgrade.
   - The router is fully upgraded. For the detailed information, please refer to the firmware release note of v2.20b03.