DIR-866L Firmware Patch Notes

Firmware: FW1.03.B01
Hardware: A1
Date: 2015/07/16

Note:
None

Problems Resolved:

- **Fixed Security vulnerability**
  - HTTP Buffer Overflow - reported by Samuel Huntley - samhuntley84@gmail.com

Enhancements:
None

Known Issues:
None

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.