DIR-868L Firmware Release Notes

Firmware: 1.20B07 Hotfix
Hardware: Ax
Date: August 26, 2020

Problems Resolved:

1. Unauthenticated RCE (LAN-Side) via UPNP
    a. CVE-2019-20215
    b. CVE-2019-20216
    c. CVE-2019-20217

2. Unathenticated remote command execution on the LAN-Side
    a. CVE-2019-17621
    b. CVE-2019-20213

3rd Party Report:

- Miguel Mendez Z. — (s1kr10s) - Research Center at Telefónica Chile
- Pablo Pollanco — (secenv) - Research Center at Telefónica Chile

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.