DIR-885L Firmware Release Notes

Firmware: FW v1.11.B07_WW
Hardware: REV. A1
Date: 2016/05/05

Note:
None

Problems Resolved:

1. Fixed possible Website Filters not working in some environment.
2. Fixed possible display of incorrect USB3.0 LED status
3. Fixed the possibility to enable Guest Zone unexpectedly
4. Fixed Graphical UI errors
5. Corrected Auto Reboot behavior
6. Fixed Security Vulnerability:
   Stack-based buffer overflow exploit - CVE-2016-5681 VU#332115 – Reported by Daniel Romero - NCC Group - Street: Calle Serrano Galvache Number: 56 Building: Abedul Floor: 4th, Madrid, 28033

   For additional details please visit:
   http://supportannouncement.us.dlink.com/announcement/publication.aspx?name=SAP10063

Enhancements:

1. Support MU-MIMO [BETA Stage].
2. Support Wireless Bridge mode.

Known Issues:
None