DIR-890L/R Firmware Patch Notes

Firmware: FW1.11b02_beta01
Hardware: A1
Date: 2017/05/19

Note:
Reported by: Igor Kirillov (i.kirillov at embedi dot com)
from Embedi

Problems Resolved:

1. Cgibin file incorrectly parses parameters sent by POST-request thus it allows an unauthorized user to execute php-sqript which discloses admin login and password.

Enhancements:
None

Known Issues:
None

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.