DIR-895L Firmware Release Notes

Firmware: FW1.02.B07 (Release)
Hardware: A1
Date: 2016/03/21

Note:
None

Problems Resolved:
1. Fix QoS rules fail after changing reserved IP
2. BT endurance improvement
3. Improved 2.4GHz connection in a noisy environment
4. Fixed enable/disable function issue on Virtual Server & Port Forward
5. Fixed STA data rate would become 54Mb

Enhancements:
None

Known Issues:
1. STA could not get IP address via repeater while router enabled SmartConnect (Manually connect to router within range extender GUI will still work)

Firmware: FW1.00.B11 (Release)
Hardware: A1
Date: 2015/12/28

Note:
First Release

Problems Resolved:
None

Enhancements:
None

Known Issues:
None