D-Link
BUILDING NETWORKS FOR PEOPLE

DIR-X5460 A1 Firmware Release Notes

Firmware: 1.01B02

Hardware: A1

Date: 2020/6/5

Note:

Problems Resolved:

1. Fixed LACP bugs.
2. Fixed IPv6 PPPoE disconnection issue when connecting to a specific ISP in Canada.
3. Fixed the problem that DNS is not available in PPPoE dial-up IPv6 environment.

Enhancements:

Add support of EU, AU country code

Known Issues:

1. When WPS 2.4 G and 5 gled blinking frequency is not stable, sometimes fast sometimes slow
2. USB sharing. When the UPnP media server is turned on, viewing pictures through windows mediaplay can only recognize the pictures in JPG format, but other formats such as BMP and PNG cannot
3. AOS can't select the corresponding level by clicking the priority ID under SG country code. However, it can operate normally on the web page. Test Samsung S9.
4. UPnP port opened and camera can't be viewed from PC2 via UPnP.

Firmware: 1.00B05

Hardware: A1

Date: 2020/5/12

Note:

This version only supports CA and NA country code.

Problems Resolved:

4. First official release

Enhancements:

N/A

Known Issues:

1. When WPS 2.4 G and 5 gled blinking frequency is not stable, sometimes fast sometimes slow
2. USB sharing. When the UPnP media server is turned on, viewing pictures through windows mediaplay can only recognize the pictures in JPG format, but other formats such as BMP and PNG cannot
3. AOS can't select the corresponding level by clicking the priority ID under SG country code. However, it can operate normally on the web page. Test Samsung S9.
4. UPnP port opened and camera can't be viewed from PC2 via UPnP.