Firmware Version: V03.00.4800.33
Prom Code Version:
Published Date: 2012/4/17

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V03.00.4800.28	2011/9/22	DNS-1550-04	A1
V03.00.4800.33	2012/4/17	DNS-1550-04 DNS-1250-04 DNS-1250-06	DNS-1550-04 rev. A1 and A2 DNS-1250-04 A1 DNS-1250-06 A1

Upgrading Instructions:

N/A. please follows procedures in user manual

New Features:

Fireware Version	New Features
V03.00.4800.28	Initial Release for DNS-1550-04
V03.00.4800.28	Initial Release for DNS-1250-04/ DNS-1250-06.

Problems Fixed:

Firmware Version	Problems Fixed
V03.00.4800.28	N/A
V03.00.4800.29 (Non-release version)	1. RB-200325: FW_SFTP can login DNS-1250/ 1550 and see all data in NAS. 2. RB-200765: MacOS 10.7 can't access DNS-1250/ 1550 AFP function. 3. RB-200907: "successful"wording issue on iSCSI PING 4. RB-200908: "Alias must contain only alphanumeric characters, blank spaces and underscores." issue 5. RB-200911: "Enable Power Management" in disk array settings could not checked 6. RB-200913: "disconnect" wording issue while setting up the message alert 7. RB-200914: .adlocks folder and .backupcfg file need to be hidden from FileZilla 8. RB-200915: AD group could change AD members in wizards but could not be saved 9. RB-200916: User name could not be more than 16 characters 10. RB-200917: While NAS unit joined AD, can't create any local account 11. RB-200925: Test E-mail alert shows no messages for the user if it is

	successful or not 12. RB-200970: EVT:LUM Mapping can not be setting , when just one initiator 13. RB-200971: EVT:The firmware upgrade page will hyperplasia , when click this page during deleting filesystem 14. RB-200973: EVT:The typesetting of LD should be more smoothly 15. RB-200975: EVT:The typesetting of FW upgrade should be more smoothly 16. RB-200982: FTP setting fails 17. RB-200990: E-mail alert with SMTP Authentication function does not work with Gmail 18. RB-201008: [FW] Can't support Windows 2008 R2 AD server when setup server base on Windows 2008R2. 19. RB-201205: NAS DNS-1250-04 and DNS-1550-04 remote replication failure 20. RB-201224: iSCSI session is created between two NAS units, promise node name will appear
V03.00.4800.30 (Non-release version)	Remove all "Vendor's name and logo" on firmware and software
V03.00.4800.31 (Non-release version)	1. RB-200925: Test E-mail alert shows no messages for the user if it is successful or not 2. RB-201439: iSCSI connection between two NASes, iqn name is missing 3. RB-201536: Dashboard shows the wrong icon highlighted 4. RB-201524: Click on GUI, it sends the user back to login page. 5. RB-201561: No need for firmware update reminder on GUI 6. RB-201548: SNMP settings not saving after reboot.
V03.00.4800.32 (Non-release version)	1. RB-200911: [PTT/Dlink] "Enable Power Management" in disk array settings could not checked 2. RB-201523: [PTT/Dlink][Suggestion] Poor grammar - "is fails" It should be "This operation has failed" 3. RB-201528: [PTT/Dlink][suggestion] Poor grammar - "Move Successfull" when moving files on Web file manager 4. RB-201939: [PTT/D-LINK] Smart log can not be enabled 5. RB-201941: [PTT/Dlink] Email alert can't work on Hinet SMTP: msa.hinet.net 6. RB-201938: [PTT/Dlink] Remote backup can only "SYNC" 7. RB-202066: [PTT/Dlink] Firmware can't be updated when the unit is on safe mode 8. RB-202059: [PTT/Dlink] When the GUI stays in "device", press F5 might go somewhere else
V03.00.4800.33 (Release version)	1. RB-200911: "Enable Power Management" in disk array settings could not checked 2. RB-202059: When GUI stays in "device", press F5 might go somewhere

	else 3. RB-202450: the size for the file system is "-1" 4. RB-202327: Enabling iscsi lun masking cause boot sequence error 5. RB-202223: User "administrator" is unable to shutdown the device 6. RB-202189: Specific Delete DA steps will Crash 7. RB-202188: Enable Smart of Function description error 8. RB-202186: WPPe_Physical Drive setting should be synchronized in front view 9. RB-202185: WPPe_Offline function should remove in front view.

Known Issues:

Firmware Version	Known Issues
V03.00.4800.28	N/A
V03.004800.33	N/A

Related Documentation:

N/A