DWA-182 Firmware Release Notes

Firmware: FW3.06b04 (Release)
Hardware: C1
Date: 2016/02/17

Note:
None

Known Issues:
None

Enhancements:
1. Support for Windows 10
2. Updated WHQL driver

Problems Resolved:
3. Fix USB speed issue: USB speed limited to USB 2.0 standard when operating in 5GHz band

---

Firmware: FW3.03b04 (Release)
Hardware: C1
Date: 2015/01/23

Note:
None

Known Issues:
4. Reconnection issues when changing USB mode from USB 2.0 to USB 3.0
5. Wireless utility will disappear 10s-15s when changing USB mode
6. XP/XP64 do not support utility, so users can't use the utility to create the WPS connection
7. Disappearing Win8 remove hardware icon
8. When the security is Shared key, the configuration of Utility profile is not accordant.

Enhancements:
1. Updated WHQL driver.

Problems Resolved:
None