DAP-1860 Firmware Release Notes

Firmware: 1.04B05 Hotfix
Hardware: Ax
Date: July 16, 2020

Problems Resolved:

- ZDI-CAN-10084: D-Link DAP-1860 HNAP SOAPAction Command Injection Remote Code Execution Vulnerability

3rd Party Report:

chung96vn - Security Researcher of VinCSS (Member of Vingroup) working with Trend Micro Zero Day Initiative

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.