Firmware Version: V1.02.00
Prom Code Version:
Published Date: 2015/10/1

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.02.00	2015/10/1	DCS-2210L	A1
V1.01.00	2015/8/17	DCS-2210L	A1
V1.00.10	2015/5/15	DCS-2210L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:
1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse… and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.02.00	1. Updated Digital Signature 2. Updated mydlink agent to 2.0.19-b60n
V1.01.00	1. Update the mydlink agent to 2.0.19-b60
V1.00.10	Initial Release. mydlink agent v2.0.19-b02

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.00	1. Fixed the Cross-Site Scripting(XSS) issue 2. Fixed the security issue of tunneling RTSP streaming over HTTP 3. Fixed the Network Time Protocol daemon(ntpd) vulnerabilities issue

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A