DCS-7010L

Firmware Release Notes

Version : 1.00.05
Agent Version: 2.0.15-b16
Date : 2012/7/31
Author : Joe kuo

First Release

 # New Features: None

 # Enhancements: None

 # Problems Resolved:

1. Fixed device will reboot when system have no memory.

#Known Issue and Limitation: None

Version	**: 1.00.04**
Date	**: 2012/7/23**
Author	**: Joe kuo**

First Release

 # New Features: None

 # Enhancements: None

 # Problems Resolved:

1. Fixed timezone table language display error.
2. Add timezone table chs and cht.

#Known Issue and Limitation: None

Version : 1.00.03
Date : 2012/7/12
Author : Joe kuo

First Release

 # New Features: None

 # Enhancements: None

 # Problems Resolved:

3. Fixed the avi files size abnormal of event trigger.
4. Fixed the DHCP server can't get the device name of DCS-2310L.

#Known Issue and Limitation: None

Version : 1.00.02
Date : 2012/7/11
Author : Joe kuo

First Release

 # New Features: None

 # Enhancements: None

 # Problems Resolved:

1. Fixed the avi files size abnormal of event trigger.

#Known Issue and Limitation: None

Version	**: 1.00.01**
Date	**: 2012/07/03**
Author	**: Joe.kuo**

First Release

 # New Features: None

 # Enhancements: None

 # Problems Resolved: None

 # Known Issue and Limitation: None