Firmware Version: V2.10
Prom Code Version:
Published Date: 2014/2/14

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01	2010/12/22	DCS-7110	A1
V1.10	2012/8/01	DCS-7110	A2
V1.20	2012/8/31	DCS-7110	A3
V2.10	2014/2/11	DCS-7110	A3

Upgrading Instructions:

Follow normal procedure to upgrade network camera FW from web UI.

New Features:

Fireware Version	New Features
V1.10	Support PPPoE CHAP
V1.10	Approval by ONVIF test tool v1.02.4
V1.20	Support NIPCA motion detection cgi
V2.10	1. Increase character of camera name to 64 bytes 2. Support ONVIF test tool v12.12 3. Add "keep network setting" function when restore the camera. 4. Support motion detection for D-ViewCam management.

Problems Fixed:

Firmware Version	Problems Fixed
V1.10	D-Track no. DBG11060237 & DRU20110614000005, camera doesn't respond by the default IP address
	Image noise issue in night mode
V1.20	DBG10120098 : Add default icon in Image Settings (Profile 1)
	DBG11110304 : After disable DUT HTTPS secure connection, DUT redirect to HTTP webpage with HTTPS port
	DBG11110317 : After change logo graph, the title name would overlap the left logo graph in live view page.
	DBG11110318 : The copy button in HTML Code Examples page didn't work.
	DBG12010013: When change DUT HTTP/RTSP port to 8081/5544, browse DUT H.264 using QuickTime plugin HTML code example by FireFox would show connection failed.
	DBG11100155 : After firmware upgrade the logo graph settings would disappear.
	DBG11100146 : Recording notify message file didn't show the right folder path of network storage server. (Remove the path information)
	DBG11110280 : The values of default and output frame size setting cannot be synchronized.
V2.10	1. Security hole issue 2. Camera can't boot up after downgrade the FW to v1.20. [DBG13080429] 3. D-View 6.0 couldn't recognize the camera after enable the SNMP. [DBG13080407] 4. Change wording in html code example "H.264/MPEG4 using QuickTime plugin **for**

	Firefox". [DBG11120229] 5. Cycling recording can't check and delete the oldest file. [HQ20130321000013] 6. Too many trigger sent when motion detect function is enable. [HQ20130108000014]

Known Issues:

Firmware Version	Known Issues
N/A	

Related Documentation:

N/A