DGS-3000-10TC Firmware Patch Notes

Firmware: FW1.20B002
Hardware: Ax
Date: November 14, 2017

Note:
There are Cross-Site Scripting and Content Spoofing vulnerabilities in the D-Link DGS-3000-10TC and DGS-3200-16. Original disclosure by websecurity.com.ua.

Problems Resolved:

1. Cross-Site Scripting (WASC-08):
http://site/html/errorpage.html?%22;alert(document.cookie);//

2. Cross-Site Scripting (WASC-08):
http://site/html/errorpage.html
Attack via header "Referer: javascript:alert(document.cookie)".

3. Content Spoofing (WASC-12):
http://site/html/errorpage.html?You%20are%20hacked
Text Injection attack is possible.

Enhancements:
None

Known Issues:
None