DIR-1260 AC 1200 Wi-Fi Router

Version: V1.01B01

Hardware: A1

Date: 2020/11/12

Problems Resolved:
1. Set default encryption to WPA2 AES
2. Update js file
3. Update Power table
4. Upgrade mydlink agent
5. Support DFS channels under IN country code
6. Fixed QoS and quickvpn issue for DTW
7. Based on MTK suggestion to add patch and modify watchdog timing

Enhancement:

N/A