DIR-1360 Firmware Release Notes

Firmware: v1.01B03
Hardware: A1
Date: April 20, 2019

Note:

1. The first official version released.

Problems Resolved:

1. Support for SSL mailbox to solve the problem receive logs with Gmail mailbox.

2. Solve a Quickvpn problem raised by D-track. When SPI is turned on, the Quickvpn dialing of iOS fails.

3. Solve the problem that the long lease period of DHCPv6 server on D-track device leads to abnormal radvd process and the client can't get the IPv6 address.

4. Fixed the problem of unsuccessful preservation of firewall ipv4/ipv6 rules.

5. Fixed the problem that UPnP could not find by changing LAN's IP address.

6. Fixed radvd process does not send RA message because the time zone reset time is advanced after the access to WAN port is correct.

7. Add mydlink's key and PEM backup mechanism. If the key or PEM is empty or missing, it can be read and restored from the backup area.

8. Restore the factory settings operation has not completed the abnormal power off, the device can normally restore the default configuration when boot-up.

9. Modify the channel list corresponding to the IN country code according to the document <PSD-001-01009_D-Link Wi-FI frequency table_20190102.pdf>

Enhancements:

N/A

Known Issues:

N/A