![D-Link — Building Networks for People]

DIR-1950 Firmware Release Notes

Firmware: v1.11B03

Hardware: A1

Date: 2021/05/24

Enhancements:

- N/A

Problems Resolved:

- Hotfix HQ20210506000001 FOTA Error push notification bug.

- Hotfix HQ20210419000005 There will be a redundant Parental Control Profile if setting a profile under FW 1.00B17 and then upgrading it to v1.10B24.

- Hotfix HQ20210505000005 WPA2& WPA2/3 Mode 2.4G issue.(some ios device can't link when security type is WPA3)

Known Issues:

- DIR-1750,DIR-1950 specification does not support mesh together.

- DIR-1750, DIR-1950 APP is designed as router flow, not COVR APP flow

- This version of FW disables 802.11r to achieve maximum compatibility with clients.