DIR-615 Firmware Patch Notes

Firmware: FW6.07.B01_WW
Hardware: F(x)
Date: 2015/05/11

Note:
None

Problems Resolved:

- **Fixed Security vulnerabilities as described on [SAP10055]**
    - Authentication Bypass
    - Remote Code Execution

For details visit:
http://securityadvisories.dlink.com/security/publication.aspx?name=SAP10055

Enhancements:
None

Known Issues:
None