DIR-636L Firmware Release Notes

Firmware: FW1.05.B09_BETA
Hardware: REV. A1
Date: 2015/03/09

Note:
None

Problems Resolved:

- CVE-2015-1187: Remote Command Injection - Incorrect Authentication
- The reported exploit for remote code execution in ping.ccp
- The reported exploit in UDPServer / MP Daemon
- File Disclosure Issue
- The reported exploit in diagnostic hooks below:
    - tftpd_ready.txt
    - chklst.txt
    - wps_default_pin.txt
    - usb_connect.txt
    - wps_btn.txt
    - reset_btn.txt
    - reboot_btn.txt
    - calibration_ready24G.txt
    - calibration_ready5G.txt
    - restore_default_finish.txt
    - set_mac_finish.txt
    - test_mode.txt
    - wifist.txt

- The exploit of DNS hijacking in “fwupgrade.ccp”

Enhancements:
None

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.