DIR-830L Firmware Release Notes

Firmware: FW1.01.B02_BETA
Hardware: REV. A1
Date: 2015/03/05

Note:
None

Problems Resolved:

- The reported exploit for remote code execution in ping.ccp
- The reported exploit in UDPServer / MP Daemon
- File Disclosure Issue
- The reported exploit in diagnostic hooks below:
    - tftpd_ready.txt
    - chklst.txt
    - wps_default_pin.txt
    - usb_connect.txt
    - wps_btn.txt
    - reset_btn.txt
    - reboot_btn.txt
    - calibration_ready24G.txt
    - calibration_ready5G.txt
    - restore_default_finish.txt
    - set_mac_finish.txt
    - test_mode.txt
    - wifist.txt

- The exploit of DNS hijacking in “fwupgrade.ccp”

Enhancements:
None

Known Issues:
None