DIR-842 Firmware Release Notes

Firmware: v3.13B05
Hardware: Rev. Cx
Data:November 1, 2019

Note:

- The firmware version is advanced to v3.13.
- The firmware v3.13 must be upgraded from the transitional version of firmware v3.02b03_middle.

Problem Resolved:

- Fix ipv6 issue in special environment.

Enhancements:

- Support WPA3/SAE.
- Force user to setup admin password during wizard flow.
- Support tftpd64.