# DIR-860L Firmware Patch Notes

**Firmware: FW1.09.B06**
**Hardware: A1**
**Date: 2015/04/11**

**Note:**
None

**Problems Resolved:**

- **Fixed Security vulnerabilities as described on [SAP10054]**
  - HNAP Privilege Escalation
  - Command Injection

**For details visit:**
**http://securityadvisories.dlink.com/security/publication.aspx?name=SAP10054**

**Enhancements:**
None

**Known Issues:**
None

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.