DIR-895L Firmware Release Notes

Firmware: FW1.02.B04 (Beta)
Hardware: A1
Date: 2016/01/25

Note:
None

Problems Resolved:
1. Fix QoS rules fail after changing reserved IP
2. Client could not get IP address via dual band repeater while router enabled SmartConnect

Enhancements:
1. P2P endurance improvement

Known Issues:
None

Firmware: FW1.00.B11 (Release)
Hardware: A1
Date: 2015/12/28

Note:
First Release

Problems Resolved:
None

Enhancements:
None

Known Issues:
None