

## **DAP-1330 Firmware Release Notes**

**Firmware: v1.13B01 BETA**

**Hardware: A1**

**Date: Jan. 20<sup>th</sup>, 2020**

### **Problems Resolved:**

- Fix few issues on Chrome/IE browser.
- Fix some IPv6 issue.
- Fix HT20/40 consistence issue.
- Fix potential security issue including WPA2 fixed.
- Fix management issue on Web page.
- ZDI-CAN-9554 - HNAP Authentication Implementation (chung96vn - Security Researcher of VinCSS (Member of Vingroup) working with Trend Micro Zero Day Initiative)

### **Enhancements:**

- Support IPv6.
- Support auto channel on Ethernet mode.
- Improve setup process.
- Disable 11d information.
- Improve Firmware upgrade process.

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.