



DAP-1360 Firmware Release Note

Firmware: v2.11 (build b23)

Hardware: B1

Problems Resolved:

1. Fixed: WPS issue.
 2. Added: Zero configuration in AP mode
-

Enhancements:

1. NA
-