



DAP-1360 Firmware Release Notes

Firmware: 6.14B01 EU Hotfix

Hardware: Fx

Date: May 11, 2020

Problems Resolved:

- Command Bypass

Security incident Report:

Daniel Schlör, M. Sc.
Chair of Data Science (LSX)
Institute of Computer Science
University of Würzburg

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.