



Firmware Version: 2.01rc012

Published Date: 2014/09/05

Content:

Upgrading Instructions:.....	2
Upgrading by using Web-UI.....	2
New Features:	3
Changes of MIB & D-View Module:	3
Problems Fixed:.....	3
Known Issues:.....	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.00rc006	2014/04/17	DAP-2360	B1


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



The screenshot displays the D-Link DAP-2360 Web-UI interface. The top navigation bar includes links for Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree structure with categories like Basic Settings (Wireless, LAN, IPv6), Advanced Settings, and Status. The main content area is titled 'System Information' and lists the following details:

Parameter	Value
Model Name	DAP-2360
Firmware Version	2.01 09:51:29 07/01/2014
System Name	D-Link DAP-2360
Location	
System Time	01/01/1970 00:01:26
Up Time	0 Days, 00:1:27
Operation Mode	Access Point
MAC Address	c4:a8:1d:94:8e:28
SSID 1~7	c4:a8:1d:94:8e:29 ~ c4:a8:1d:94:8e:2f
IP Address	192.168.0.50

New Features:

1. Support CWM phase I feature

Changes of MIB & D-View Module:

Problems Fixed:

Firmware Version	Problems Fixed
V2.01	1. Add AU/CN country code

Known Issues:

Firmware Version	Known Issues
V2.01	None

Related Documentation:

- DAP-2360 User Manual v2.01