



DAP-2660 Firmware Hotfix Release Notes

Firmware: 2.00B05r148

Hardware: Ax

Date: 8/24/2023

FIRMWARE MOVED TO LEGACY SITE, <https://legacy.us.dlink.com/>

Problems Resolved:

Buffer Overflow Vulnerabilities

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.