



Firmware Version: 1.00r022
Published Date: 2020/04/29

Content:

Upgrading Instructions: 2

 Upgrading by using Web-UI..... 2

New Features: 3

Changes of MIB & D-View Module: 3

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter <http://dap2682.local> to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
3. Enter administrator's username and password, user name and password are "admin" by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



The screenshot shows the D-Link DAP-2682 Web-UI interface. The top navigation bar includes links for Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2682, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

Model Name	DAP-2682
Firmware Version	v1.00 19:48:09 04/18/2020
System Name	dap2682
Location	
System Time	04/29/2020 15:36:38
Up Time	0 Days, 00:1:45
Operation Mode(2.4GHz)	Access Point
Operation Mode(5GHz)	Access Point
MAC Address(2.4GHz)	58:d5:6e:06:60:e0
MAC Address(5GHz)	58:d5:6e:06:60:e8
LAN IP Address	192.168.0.106
Router Mode	Off

New Features:

1. First release

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V1.00	None

Known Issues:

Firmware Version	Known Issues
V1.00	None

Related Documentation:

DAP-2682 manual v1.00