



Firmware Version: 1.10rc035
Published Date: 2014/09/05

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... 2

New Features:..... 2

Changes of MIB & D-View Module:..... 2

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:


Firmware Version	Date	Model	Hardware Version
v1.00	2013/11	DAP-2695	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.
To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. Update wireless driver to 10.2.85
2. Support CWM phase 1 feature

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V1.10	[AP Array] : Fix the Signal Band AP set to Master, After sync, 5G band sync issue. [Login Page Upload] : Fix after set settings the image will disappear [Help] : Add help of MAC By Pass function. [AP Array] : Fix the bug when set one Master AP to Backup Master role [AP Array] : Fix one member leave and then add into the group again, the config can't sync [Network Utilization] : Fix this function doesn't work in 5G band [Throughput] : Fix WDS with WPA2-AES can't run over 5 minutes in 5G [LED] : Fix 5G LED not off when 5G radio off - Fix client info does not correct when 11AC when connected

Known Issues:

Firmware Version	Known Issues

Related Documentation:

- DAP-2695 User Manual v1.10