



Firmware Version: 2.03.000
Boot Code Version: 1.00
Nuclias Portal Version: 2.2.0
Published: May. 15, 2020

These release notes include important information about D-Link Nuclias Access Point firmware revisions. Please verify that these release notes are correct for your Access Point:

Content:

Revision History and System Requirement: 2

Upgrade Instructions: 2

New Features: 2

Changes of Command Line Interface: 3

Problem Fixed: 3

Known Issues: 4

Related Documentation: 4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version	Remark
V2.03.000	18-May-2021	DBA-3620P	A1	Lab in for Publish
V2.02.000	16-Jan-2021	DBA-3620P	A1	Offical Release
V2.01.000	15-Sept.-2020	DBA-3620P	A1	Offical Release
V2.00.002	20-Jun.-2020	DBA-3620P	A1	Offical Release
V2.00.001	20-Apr.-2020	DBA-3620P	A1	1st release

Upgrade Instructions:

When the device added to Nuclias portal, the Nuclias portal will automatically update the Access Point firmware to the latest version. User can go to SETTINGS→Firmware → ACCESS POINT UPGRADE to change the firmware upgrade policy and there are three options:

ACCESS POINT UPGRADE

DBA-1210P

DBA-1510P

DBA-1520P

DBA-2520P

DBA-2620P

DBA-2720P

DBA-2820P

DBA-3620P

DBA-3621P

DBA-X2830P

Model no. DBA-3620P

Current version

Upgrade version

☒ Follow upgrade window
☐ Reschedule the upgrade to
☐ Perform the upgrade now

#	Model no.	Devices	Current firmware version	Firmware status	Upgrade schedule	Last upgrade time
1	DBA-3620P	0		Up to date	Follow upgrade window (Wednesday; 4:00 PM)	01/01/1970

New Features:

Firmware Version	New Features
V2.03.000	1. Support RADIUS Accounting Interim-Update Parameters. 2. Support Session-timeout of Captive Portal from RADIUS server. 3. Captive Portal Enhancement
V2.02.000	1. Add NAS-ID attribute
V2.01.000	1. Support Seamless Roaming

V2.00.002	1. Add 802.11ax neighbor AP detection. 2. Add customized LLDPD.
V2.00.001	First release

Changes of Command Line Interface:

The section below only shows command line changes that may bring backward compatibility issues with configuration settings for previous version of firmware.
Any new feature commands that do not have backward compatibility issues are not included in the below section.

Firmware Version	Changes
V2.00.001	First Release

Problem Fixed:

Firmware Version	Problems Fixed
V2.03.000	- Fixed Incorrect SSID schedule if mixed on/off. - Fixed WPA3 radius does not support the latest version of IOS 14.3 \& 14.4 with iphone 12 - Fixed The device will not report new channel after DFS happen - Fixed Captive Portal does not work after switching vlan with RADUIUS accounting - Device WebGUI will not return to login screen after doing reset via the local Web GUI - Fixed SSID schedule incorrect when device is changed time zone from portal
V.2.02.000	Fix WebUI did not check the incorrect IP setting

	2. Fix that client does not be disconnected at schedule off if the VAP is hidden. 3. SplashPage does not update after edit. 4. Neighbor AP function is not working when SSID is off due to schedule
V2.01.000	5. Fix user can't access Walled Garden before authentication. 6. Fix Force auto channel scan issue.
V2.00.002	1. Fixed the 5G SSID won't be able to scan when change security and Channel to WPA3 and fix channel. 2. Fixed Email auth issues after the session expired. 3. Fixed RADIUS ACCOUNTING issue for captive portal
V2.00.001	First Release

* D-Link tracking number is enclosed in ()

Known Issues:

Firmware Version	Issues	Workaround

Related Documentation:

- DBA-3620P A1 User Manual V1.0
- DBA-3620P A1 QIG V1.0
- Nuclias user manual