



DCS-1100/1130 Firmware Release Notes

Firmware:1.03-4108

Hardware: A1

Date:2010/4/15

Problems Resolved:

1. Improvement RTSP compatibility with BlackBerry mobile phone.
2. For DCS-1100 and DCS-1130, fixes some MAC address lead UPnP failure.
3. For DCS-1100 and DCS-1130, remove useless code cause incorrect IR icon on Live View web page.

Note:

Please process "Restore Factory Defaults" to make the modification affect.

Enhancements:

1. Modify "Security" graph to "Surveillance" wording graph.
2. Update copyright statement of web pages.
3. Update system check boot-up date/time and restore factory default date/time to 2010/01/01.
4. Remove 2009 select item of manually date/time settings.

Known issue:

None

Firmware:1.02-3522

Hardware: A1

Date:2009/11/20

Problems Resolved:

1. Remove incorrect help description –SDcard
2. Fine tune RTSP packages for mobile phone compatibility.
3. Resolved resume continuous snapshot to FTP when network cable replug issue.
4. Fixes using anonymous account to FTP to network storage fail issue.
5. Reset RTC to default date-time when Factory Reset.
6. Separate Java applet into 4 applets for improving video streaming performance.

7. Adjust to disable I2C interface after initial the echo canceling.

8. Fixes play_wav application in firmware to open sound device for QC testing tool testing audio out fail issue.

Note:

Please process "Restore Factory Defaults" to make the modification affect.

Enhancements:

None