



Firmware Version: V2.02.02
Published Date: 2020/07/23

Content:

Revision History: 2

Upgrading Instructions: 2

New Features: 2

Enhancements: 2

Problems Fixed:..... 3

Known Issues: 3

Related Documentation:..... 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.02.02	2020/07/23	DCS-4602EV	B1
V2.01	2018/10/29	DCS-4602EV	B1
V2.00	2018/05/04	DCS-4602EV	B1
V1.05	2017/01/06	DCS-4602EV	A1
V1.04	2016/02/02	DCS-4602EV	A1
V1.03	2015/10/12	DCS-4602EV	A1
V1.02	2015/10/05	DCS-4602EV	A1
V1.01	2015/06/30	DCS-4602EV	A1
V1.00	2015/06/16	DCS-4602EV	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in ".pkg" file format.
2. Log-in camera web UI and enter **Setup/Advanced Setup/System configuration/Firmware upgrade**
3. Click Browse... and specify the firmware file.
4. Click Upload. The camera starts to upgrade and will reboot automatically when the upgrade completes.

Notice: HW B1 is applied with different platform, the FW can't not be backward compatible with HW A1.

New Features:

Fireware Version	New Features
V2.00	New GUI (Ver. 3)

Enhancements:

Firmware Version	Problems Fixed
V2.02.02	1. TLS 1.2 2. SHA 2

Problems Fixed:

Firmware Version	Problems Fixed
V2.02.02	1. Remove ""www.dlinkddns.com"" 2. Time Sync. (2019-->2037) 3. Multicast group address could setting over 239.X.X.X 4. Synchronize the permissions of camera users and ONVIF users to solve the problem that the user account cannot obtain images 5. Wrong time digital signature of ActiveX
V2.01	1. Update digital sign 2. Bug fixed, D-Track [DRU20180711000004] – Incorrect Tab name display on “Image settings” of web UI. Tab “Image” changes to “Image and Audio” while switching to another setting items. 3. Bug fixed, D-Track [DRU20180907000001] –Incorrect input of the Network Storage Location address. 4. Bug fixed, stream issue with DNR-322L. 5. Bug fixed for D-Lab minor issues.
V1.05	1. Support ONVIF V16.07 2. Support SHA 256 3. Upgrade OpenSSL to 1.0.1t 4. Fixed minor issues
V1.04	1. Enhancement for security issue: a. Support TLS 1.1/1.2. b. CSRF protection default enable. 2. A warning message popped up for that Chrome V45 (or higher) cannot support plugin. 3. Fixed snapshot/video recording issue while browse UI in IE11. 4. Fixed flicker issue. 5. Fixed MG-SOFTcannot connect the camera via SNMPv1, SNMPv2c, or SNMPv3. 6. Fixed Curl issue -mail server SMTP authentication fail. 7. Fixed Day&Night mode not to trigger while switching in between two modes.
V1.03.00	1. Upgrade to new signing keys for fixing Code-Signing Key issue
V1.02.02	1. Fixed the security issue of tunneling RTSP streaming over HTTP 2. Fixed the Cross-Site Scripting(XSS) issue 3. Fixed the Cross-Site Request Forgery (CSFR) issue
V1.01.02	1. Fixed no live video issue when image setting at 4:3, 1280x960 / 1024x768 resolution. 2. Fixed flicking image when anti-flicker setting =50Hz 3. Remove the SD card information on Event Setup help hints page.

Known Issues:

Firmware Version	Known Issues
V2.00	Do not support H.265 decode on MAC.

Related Documentation:

N/A