



Firmware Version: V1.01.04
Prom Code Version:
Published Date: 2014/11/13

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01.04	2014/11/12	DCS-5029L	A1
V1.00.04	2014/6/16	DCS-5029L	A1

Upgrading Instructions:

Initial Version does not require, but follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.01.04	<ol style="list-style-type: none"> 1. Update agent to 2.0.18b09 2. Add 50MB/30 sec Event on SD function 3. Add 720P resolution for profile 2 4. Add support for Motion detection, direct MJPEG decoding, and Privacy masks on non-IE browsers 5. Add new DDNS selection 6. Changed display model to DCS-5222L B (no number designator) 7. Changed default timer from 60 to 90s 8. Add Default UI language detection 9. Updated Wi-fi drivers to comply with latest EU ECN 300 328 requirements
V1.00.04	Initial Release

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.04	Fixed iOS PT issues.
V1.00.04	Initial Release

Known Issues:

Firmware Version	Known Issues
V1.01.04	Due to updated security settings, initial plugin supplied at release will require a workaround to view on Safari 8. This is not a Firmware issue, however is listed with this version since this is the first firmware tested that was affected.
V1.00.04	Firmware does not follow 6-30 character password rules

Related Documentation:

N/A