



**Firmware Version:** V1.01.01  
**Prom Code Version:**  
**Published Date:** 2017/10/19

---

**Content:**

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: ..... 2

Known Issues: ..... 2

Related Documentation: ..... 2

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01.01	2017/10/18	DCS-8000LH	A1
V1.00.05	2017/7/14	DCS-8000LH	A1

## Upgrading Instructions:

NA

## New Features:

Fireware Version	New Features
V1.01.01	Update mydlink agent to v2.1.0-b89
V1.00.05	Initial Release

## Problems Fixed:

Firmware Version	Problems Fixed
V1.01.01	<ol style="list-style-type: none"> <li>1. Fix audio noise issue</li> <li>2. Support LED on/off on APP</li> <li>3. Add tdb flush for fw upgrades from Gen1 to Gen2.</li> <li>4. Fix ICR control issue</li> </ol>

## Known Issues:

Firmware Version	Known Issues

## Related Documentation:

N/A