



**Firmware Version:** V2.02.02  
**Prom Code Version:**  
**Published Date:** 2019/04/02

---

**Content:**

Upgrading Instructions:..... 2  
New Features:..... 2  
Problems Fixed: ..... 2  
Known Issues: ..... 3  
Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.02.02	2019/4/2	DCS-8000LH	A3
V2.01.03	2018/7/6	DCS-8000LH	A3
V2.00.05	2018/1/15	DCS-8000LH	A2
V1.01.01	2017/10/18	DCS-8000LH	A1
V1.00.05	2017/7/14	DCS-8000LH	A1

## Upgrading Instructions:

NA

## New Features:

Fireware Version	New Features
V2.02.02	<ol style="list-style-type: none"> <li>1. Change mydlink agent to v3.1.0-b03.</li> <li>2. Support WEP encryption</li> <li>3. Support mydlink APP rich notification feature</li> <li>4. Support mydlink APP fw manual upgrade feature</li> </ol>
V2.01.03	<ol style="list-style-type: none"> <li>1. Change mydlink agent to v3.0.0-b71.</li> <li>2. Support mydlink Requirements for IoT Agent Version 1.0.6.</li> <li>3. Add mirror and Flip functions.</li> <li>4. Support mydlink Requirements for Streaming Agent Version 0.5.1.</li> </ol>
V2.00.05	<ol style="list-style-type: none"> <li>1. Update mydlink agent to v3.0.0-b44 Support LED on/off on APP</li> <li>2. Support mydlink APP</li> <li>3. Support Alexa</li> <li>4. Support Google Assistant</li> </ol>
V1.01.01	<ol style="list-style-type: none"> <li>1. Update mydlink agent to v2.1.0-b89</li> </ol>
V1.00.05	<ol style="list-style-type: none"> <li>1. Initial Release</li> </ol>

## Problems Fixed:

Firmware Version	Problems Fixed
V2.02.02	<ol style="list-style-type: none"> <li>1. Fix Bluetooth compatibility issue (D-track DGC20180706000002)</li> <li>2. Fix motion sensitivity to 0%, it still can trigger motion detection issue.</li> <li>3. Improve image quality</li> </ol>
V2.01.03	<ol style="list-style-type: none"> <li>4. LED on/off support</li> <li>5. Disable NTP client support.</li> <li>6. OSD time is not sync with the time get from "date" command.</li> <li>7. UAP could not setup WiFi connection successfully if password has "space"</li> </ol>

	character.
V2.00.05	1. WPA2 key reinstallation attacks issue.
V1.01.01	<ol style="list-style-type: none"> <li>1. Fix audio noise issue</li> <li>2. Support LED on/off on APP</li> <li>3. Add tdb flush for fw upgrades from Gen1 to Gen2.</li> <li>4. Fix ICR control issue</li> </ol>

## Known Issues:

---

Firmware Version	Known Issues
V2.02.02	1. Privacy mode cannot be disable if enable by google assistance and then power off /power on device.
V2.00.05	1. LED on/off feature no support

## Related Documentation:

---

N/A