



**Firmware Version:** V2.04.01  
**Prom Code Version:**  
**Published Date:** 2020/06/29

---

**Content:**

Upgrading Instructions: ..... 2

New Features:..... 2

Enhancement: ..... 2

Problems Fixed: ..... 3

Known Issues: ..... 3

Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Agent Version	Date	Model	Hardware Version
V2.04.01	V3.4.2-b06	2020/6/29	DCS-8000LH	A3
V2.03.02	V3.2.7-b02	2019/10/22	DCS-8000LH	A3
V2.02.02	v3.1.0-b03	2019/4/2	DCS-8000LH	A3
V2.01.03	v3.0.0-b71	2018/7/6	DCS-8000LH	A3
V2.00.05	v3.0.0-b44	2018/1/15	DCS-8000LH	A2
V1.01.01	v2.1.0-b89	2017/10/18	DCS-8000LH	A1
V1.00.05	v2.1.0-b83	2017/7/14	DCS-8000LH	A1

## Upgrading Instructions:

NA

## New Features:

Fireware Version	New Features
V2.03.02	1. Change mydlink agent to v3.2.7-b02.
V2.02.02	1. Change mydlink agent to v3.1.0-b03. 2. Support WEP encryption 3. Support mydlink APP rich notification feature 4. Support mydlink APP fw manual upgrade feature
V2.01.03	1. Change mydlink agent to v3.0.0-b71. 2. Support mydlink Requirements for IoT Agent Version 1.0.6. 3. Add mirror and Flip functions. 4. Support mydlink Requirements for Streaming Agent Version 0.5.1.
V2.00.05	1. Update mydlink agent to v3.0.0-b44 Support LED on/off on APP 2. Support mydlink APP 3. Support Alexa 4. Support Google Assistant
V1.01.01	1 .Update mydlink agent to v2.1.0-b89
V1.00.05	1. Initial Release

## Enhancement:

Firmware Version	Problems Fixed
V2.04.01	1. Enhance camera security. 2. Change camera privacy mode LED behavior to be solid orange

	<ol style="list-style-type: none"> <li>3. Change camera upgrading firmware LED to be blinking red and green in sequence.</li> <li>4. Change camera connected to mydlink LED to be solid green.</li> </ol>
--	---

## Problems Fixed:

Firmware Version	Problems Fixed
V2.03.02	<ol style="list-style-type: none"> <li>1. Remove TLS v1.0 and v1.1 support.</li> <li>2. Fix BLE command injection.</li> </ol>
V2.02.02	<ol style="list-style-type: none"> <li>3. Fix Bluetooth compatibility issue (D-track DGC20180706000002)</li> <li>4. Fix motion sensitivity to 0%, it still can trigger motion detection issue.</li> <li>5. Improve image quality</li> </ol>
V2.01.03	<ol style="list-style-type: none"> <li>6. LED on/off support</li> <li>7. Disable NTP client support.</li> <li>8. OSD time is not sync with the time get from "date" command.</li> <li>9. UAP could not setup WiFi connection successfully if password has "space" character.</li> </ol>
V2.00.05	<ol style="list-style-type: none"> <li>1. WPA2 key reinstallation attacks issue.</li> </ol>
V1.01.01	<ol style="list-style-type: none"> <li>1. Fix audio noise issue</li> <li>2. Support LED on/off on APP</li> <li>3. Add tdb flush for fw upgrades from Gen1 to Gen2.</li> <li>4. Fix ICR control issue</li> </ol>

## Known Issues:

Firmware Version	Known Issues
V2.02.02	<ol style="list-style-type: none"> <li>1. Privacy mode cannot be disable if enable by google assistance and then power off /power on device.</li> </ol>
V2.00.05	<ol style="list-style-type: none"> <li>1. LED on/off feature no support</li> </ol>

## Related Documentation:

N/A