



Firmware Version: V2.07.01 Agent Version: 3.5.20-b01 Published Date: 2021/11/03

Content:

Revision History:	. 2
New Features:	. 2
Enhancements:	. 3
Problems Fixed:	. 3
Known Issues:	. 4
Related Documentation:	. 4



Revision History:

Firmware Version	Agent Version	Date	Model	Hardware Version
V2.07.01	3.5.20-b01	2021/11/03	DCS-8000LH	A3
V2.06.03	3.5.18-b01	2021/05/20	DCS-8000LH	A3
V2.05.01	3.5.3-b06	2020/08/25	DCS-8000LH	A3
V2.04.01	3.4.2-b06	2020/06/29	DCS-8000LH	A3
V2.03.02	3.2.7-b02	2019/10/22	DCS-8000LH	A3
V2.02.02	3.1.0-b03	2019/04/02	DCS-8000LH	A3
V2.01.03	3.0.0-b71	2018/07/06	DCS-8000LH	A3
V2.00.05	3.0.0-b44	2018/01/15	DCS-8000LH	A2
V1.01.01	2.1.0-b89	2017/10/18	DCS-8000LH	A1
V1.00.05	2.1.0-b83	2017/07/14	DCS-8000LH	A1

System Requirement (Minimum HW Requirement):

System Minimum Requirements		
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.	
Network Requirements	At least 1.5Mb upload bandwidth per camera.	
Minimum Requirements	Compatible with iPhone and iPad using iOS 11 or higher Compatible with Android smartphones and tablets using Android 5.0 or higher	

New Features:

dlinkigreen

Firmware Version	New Features
	1. Support WEP encryption
V2.02.02	2. Support mydlink APP rich notification feature
	3. Support mydlink APP FW manual upgrade feature
	1. Support mydlink Requirements for IoT Agent Version 1.0.6
V2.01.03	2. Add mirror and Flip functions.
	3. Support mydlink Requirements for Streaming Agent Version 0.5.1
	1. Support LED on/off on APP
V2.00.05	2. Support mydlink APP
	3. Support Alexa



	4. Support Google Assistant
V1.00.05	1. Initial Release

Enhancements:

Firmware Version	Enhancements
V2.07.01	1. Fixed WiFi FragAttack vulnerabilities.
V2.06.03	1. Switches BLE off after device setup for enhanced wireless security
	2. Disables support for less secure ciphers
	3. Updates to improve live view connection quality
	4. Supports partial firmware upgrade feature
V2.05.01	1. Improves compatibility with revamped mydlink app
	1. Enhance camera security
V2.04.01	2. Change camera privacy mode LED behavior to be solid orange
	3. Change camera up grading firmware LED to be blinking red and green in
	sequence
	4. Change camera connected to mydlink LED to be solid green

Problems Fixed:

Firmware	Problems Fixed
Version	
V2.06.03	 Fixed DBG21040342: When the Wi Fi connection change process times out, the device LED continues to display an incorrect red indicator despite being reconnected to the original AP
V2.03.02	 Remove TLS v1.0 and v1.1 support Fix BLE commend injection
V2.02.02	 Fix Bluetooth compatibility issue (D track DGC20180706000002) Fix motion sensitivity to 0%, it still can trigger motion detection issue. Improve image quality
V2.01.03	 LED on/off support Disable NTP client support OSD time is not sync with the time get from "date" command UAP could not setup WiFi connection successfully if password has "space" character
V2.00.05	1. WPA2 key reinstallation attacks issue
V1.01.01	 Fix audio noise issue Support LED on/off on APP Add TDB flush for FW upgrades from Gen1 to Gen2. Fix ICR control issue





Known Issues:

Firmware Version	Known Issues
N/A	N/A

Related Documentation:

N/A

