



Software Version: V1.04.00
Agent Version: V3.1.0-b05
Published Date: 2019/02/25

Content:

Revision History:..... 2

New Features: 2

Problems Fixed:..... 3

Known Issues: 3

Related Documentation: 4

Revision History:

Software Version	Date	Model	Hardware Version
V1.00.05	2018/03/05	DCS-8010LH	A1
V1.01.04	2018/03/30	DCS-8010LH	A1
V1.02.02	2018/6/19	DCS-8010LH	A1
V1.03.01	2018/11/15	DCS-8010LH	A1
V1.04.00	2019/02/25	DCS-8010LH	A1

System Requirement (minimum HW requirement)

System Minimum Requirements	
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 1MByte upload bandwidth per camera.
Minimum Requirements	Compatible with iPhone and iPad using iOS 9 or higher Compatible with Android smartphones and tablets using Android 4.3 or higher

New Features:

Software Version	New Features
V1.00.00	Networking Protocol: - Bonjour - RTSP Server - NIPCA - LANDAP - Mydlink Cloud service Video Encode: - H.264: 1080P (1920 x 1280) : 30fps And 720P (1280 x 720) : 15fps - MJPEG : 720P (1280 x 720) : 1fps - JPEG for still image 720P (1280 x 720) - H.264 Support CVBR or CBR Audio Encode: Algorithm Supported: - OPUS - AAC Detection: - Sound Detection

	• Motion Detection 5. D&N Mode • Auto • Manual settings (Day/Night) 6. Recording format: • TS 7. BLE for setup 8. Remote upgrade

Enhancements:

Firmware Version	Problems Fixed
V1.00.00	NULL
V1.04.00	1. Update the agent up to V3.1.0-b05 2. Support firmware upgrade manually 3. Support new function "Rich notification"

Problems Fixed:

Software Version	Problems Fixed
V1.00.05	NULL
V1.01.04	1. Increased the volume of speaker about 6dB 2. When SSID is hidden, in site survey will show blank. 3. Wi-Fi list doesn't sort during site survey procedure. 4. Modified default date to 2000/01/01 00:00:00 5. Video clip in SD could not recycle once disk full, and this issue could fix by reboot camera.
V1.02.02	1. Improved the brightness of the image. 2. Increased the volume of the speaker around 6dB. 3. Increased the volume of speaker 4. Fixed image drop phenomenon when user use Google Home to check video.
V1.03.01	1. Improve image quality. 2. Reduce background noise. 3. Fixed LG mobile could not work with DCS-8010LH.
V1.04.00	1. Wi-Fi encryption start to support WEP and No Password

Known Issues:

Firmware Version	Known Issues
------------------	--------------

V1.01.04

1. Partial function of NIPCA did not implement into FW yet.

Related Documentation:

N/A