



Software Version: V1.05.00
Agent Version: V3.2.7-b04
Published Date: 2019/05/27

Content:

Revision History:..... 2

New Features: 2

Problems Fixed:..... 3

Known Issues: 3

Related Documentation: 3

Revision History:

Software Version	Agent Version	Date	Model	Hardware Version
V1.05.00	V3.2.7-b04	2019/05/27	DCS-8010LH	A1
V1.04.00	V3.1.0-b05	2019/02/25	DCS-8010LH	A1
V1.03.01	V3.0.0-b91	2018/11/15	DCS-8010LH	A1
V1.02.02	V3.0.0-b73	2018/6/19	DCS-8010LH	A1
V1.01.04	V3.0.0-b65	2018/03/30	DCS-8010LH	A1
V1.00.04	V3.0.0-b54	2018/03/05	DCS-8010LH	A1

System Requirement (minimum HW requirement)

System Minimum Requirements	
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 1Mbps upload bandwidth per camera.
Minimum Requirements	Compatible with iPhone and iPad using iOS 9 or higher Compatible with Android smartphones and tablets using Android 4.3 or higher

New Features:

Software Version	New Features

Enhancements:

Firmware Version	Problems Fixed
V1.05.00	1. Stream proxy support multiple client connections for Alexa or Google home 2. Update Agent version to v3.2.7-b04 3. Smart push notification when received sound event.
V1.04.00	1. Update the agent up to V3.1.0-b05 2. Support firmware upgrade manually 3. Support new function "Rich notification" 4. Wi-Fi encryption start to support WEP
V1.00.04	NULL

Problems Fixed:

Software Version	Problems Fixed

V1.03.01	1. Improve image quality. 2. Reduce background noise. 3. Fixed LG mobile could not work with DCS-8010LH. 4. If the password column is empty, FW is going to use the PIN code as the default password.
V1.02.02	1. Improved the brightness of the image. 2. Increased the volume of the speaker around 6dB. 3. Increased the volume of speaker 4. Fixed image drop phenomenon when user use Google Home to check video.
V1.01.04	1. Increased the volume of speaker about 6dB 2. When SSID is hidden, in site survey will show blank. 3. Wi-Fi list doesn't sort during site survey procedure. 4. Modified default date to 2000/01/01 00:00:00 5. Video clip in SD could not recycle once disk full, and this issue could fix by reboot camera.
V1.00.04	NULL

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A