



Firmware Version: V1.03.01
Prom Code Version:
Published Date: 2018/01/24

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.03.01	2018/01/24	DCS-8200LH	A1
V1.02.03	2016/12/12	DCS-8200LH	A1
V1.01.01	2016/06/30	DCS-8200LH	A1
V1.00.08	2016/4/22	DCS-8200LH	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.03.01	1. Update mydlink Agent to 2.2.0-b13.
V1.02.03	1. Update mydlink Agent to 2.1.0-b47 2. Support mydlink UID feature. 3. Upgrade OpenSSL to version 1.01t
V1.01.01	1. Support IFTTT - DoAction 2. Video - OSD - modified to transparent background and white color text 3. Bonjour - mDNSResponder - upgrade source code to version 567 4. Upgrade agent version to 2.0.20-b34 5. System time - modified default to 2016.05.06.000000
V1.00.08	1. Initial Release

Problems Fixed:

Firmware Version	Problems Fixed
V1.03.01	Solve WPA2 vulnerability.
V1.02.03	Shut down AP Mode until once IP success from DHCP server.
V1.00.08	Initial Release

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A