



Software Version: V1.03.00
Agent Version: V3.2.7-b04
Published Date: 2019/05/24

Content:

Revision History: 2

New Features: 2

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History:

Software Version	Agent	Date	Model	Hardware Version
V1.03.00	V3.2.7-b04	2019/05/24	DCS-8600LH	A1
V1.02.00	V3.1.0-b05	2019/02/15	DCS-8600LH	A1
V1.01.02	V3.0.1-b02	2018/12/04	DCS-8600LH	A1
V1.00.10	V3.0.0-b73	2018/08/28	DCS-8600LH	A1

System Requirement (minimum HW requirement)

System Minimum Requirements	
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 2Mbps upload bandwidth per camera.
Minimum Requirements	Compatible with iPhone and iPad using iOS 9 or higher Compatible with Android smartphones and tablets using Android 4.3 or higher

New Features:

Software Version	New Features
V1.03.00	1. Stream proxy support multiple client connections for Alexa or Google home 2. Update Agent version to v3.2.7-b04 3. Smart push notification when received sound event.
V1.02.00	1. Update the agent up to V3.1.0-b05 2. Support firmware upgrade manually 3. Support new function "Rich notification"

Enhancements:

Firmware Version	Problems Fixed

Problems Fixed:

Software Version	Problems Fixed
V1.03.00	Fix restarting router and camera at the same time, Wi-Fi reconnect failed sometimes.
V1.02.00	Wi-Fi encryption start to support WEP

V1.01.02	1. Optimized the algorithm for motion detection to reduce false alarm. 2. Enhance image quality.
V1.00.10	First version of DCS-8600LH

Known Issues:

Firmware Version	Known Issues
V1.00.10	NULL

Related Documentation:

N/A