



Firmware Version: V2.00b6
Prom Code Version:
Published Date: 2014/7/2

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.00b6	2014/7/2	DCS-930L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V2.00b6	Initial version. F/W v2.00 is not backward compatible to H/W Ax version.

Problems Fixed:

Firmware Version	Problems Fixed

--	--

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A