



**Firmware Version:** V2.12.01  
**Prom Code Version:**  
**Published Date:** 2015/10/1

## **Content:**

Upgrading Instructions: .....	2
New Features: .....	2
Problems Fixed: .....	3
Known Issues: .....	3
Related Documentation: .....	3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.12.01	2015/10/1	DCS-932L	B1,B2
V2.11.03	2015/9/1	DCS-932L	B1,B2
V2.10.03	2015/6/29	DCS-932L	B1
V2.01.03	2015/2/6	DCS-932L	B1
V2.00b6	2014/7/2	DCS-932L	B1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V2.12.01	<ul style="list-style-type: none"> <li>1. Updated mydlink agent to 2.0.19-b54n</li> <li>2. Updated Digital Signature</li> </ul>
V2.11.03	<ul style="list-style-type: none"> <li>1. Update mydlink agent to 2.0.19-b54</li> <li>2. Add the denoise mechanism to reduce the background noise</li> <li>3. Add the login check mechanism to solve Brute Force Attack issue</li> <li>4. Add Hardware Version item on the Status page of the camera's web-GUI.</li> <li>5. Change the model and model number of the UPnP properties.  <b>F/W V2.11.03 only supports D-ViewCam version as below or above.</b> <ul style="list-style-type: none"> <li>1. DCS-100 V3.6.5 + DP V1.6.13</li> <li>2. DCS-100 V4.0.4 + DP V2.0.15</li> </ul> </li> </ul>
V2.10.03	<ul style="list-style-type: none"> <li>1. Update mydlink agent to v2.0.19-b35.</li> <li>2. Support auto image setting switching mechanism for H/W B1 and B2 (or above) camera lens. (*H/W B2 or above only supports v2.10.03 or above)</li> </ul>
V2.01.03	<ul style="list-style-type: none"> <li>1. Upgrade mydlink agent to v2.0.18-b61</li> <li>2. Remove SSL, change to support TLS.</li> </ul>
V2.00b6	<ul style="list-style-type: none"> <li>Initial version.</li> <li><b>F/W v2.00 is not backward compatible to H/W Ax version.</b></li> </ul>

--	--

**Problems Fixed:**

Firmware Version	Problems Fixed
V2.11.03	<ol style="list-style-type: none"><li>1. Fixed the IE11 compatibility issue in Windows 10.</li><li>2. Change WPS LED behavior blinking time on WPS error/timeout to 10 seconds.</li><li>3. Remove the reboot function by pressing and holding the reset button in less than 3 seconds.</li><li>4. Add the pop-up warning message when the user creates an existing user account on Device Web GUI.</li><li>5. Support to auto-create FTP folder if the folder doesn't exist on FTP server.</li></ol>
V2.10.03	<ol style="list-style-type: none"><li>1. Fixed HTTPS issue that causes Day/Night control not work from portal/app.</li><li>2. Fixes the issue in which IP Cam cannot create FTP folder with FTP server on Netgear R7000 Router.</li><li>3. Fixed CGI /reset.cgi reboot command not work issue.</li><li>4. Modify Time Zone Table list to support some existing time zones changes.</li></ol>

**Known Issues:**

Firmware Version	Known Issues

**Related Documentation:**

N/A