



DIR-605L Firmware Release Notes

DIR-605L Firmware Release Notes

Firmware: FW113B06

Hardware: A1

Date: 2012/07/13

Note:

1. FW version is advanced to v1.13.

Problems Resolved:

1. Fixed the issue of time format display error in the feature of "Time and Date".
2. Fixed the hyperlink display of DDNS service.
3. Fixed the smart checking issue of device password
4. Fixed the issue that sometimes the flow will be hung after selecting time zone setting and clicking the next button.
5. Fixed the issue that using "http://dlinkrouter" can't automatically redirect to D-Link Management page in MAC OS.
6. Fixed the issue of mydlink page redirect while using setup wizard with CN/TW language pack.

Enhancements:

1. Optimized the flow of Easy Setup Wizard
2. Added NTP setting in Easy Setup Wizard
(Except for CN/TW Language Pack)