



DIR-816L Firmware Patch Notes

Firmware: FW2.06.B01

Hardware: B1

Date: 2015/04/20

Note:

None

Problems Resolved:

- **Fixed Security vulnerabilities as described on [\[SAP10054\]](#)**
 - HNAP Privilege Escalation
 - Command Injection

For details visit:

<http://securityadvisories.dlink.com/security/publication.aspx?name=SAP10054>

Enhancements:

None

Known Issues:

None

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.