



## **DIR-816L Firmware Patch Notes**

**Firmware:** FW2.06.B09 (BETA)

**Hardware:** B1

**Date:** 2015/08/10

**Note:**

None

**Problems Resolved:**

**Fixed Security vulnerability listed below:**

- Fixed a CSRF vulnerability - CVE-2015-5999 - Reported by Bhadresh Patel, Senior Security Analyst, Help AG, [bhadresh.patel@helpag.com](mailto:bhadresh.patel@helpag.com)

**Enhancements:**

None

**Known Issues:**

None

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.