



## DIR-818LW Firmware Patch Notes

**Firmware:** FW2.05.B03

**Hardware:** A1

**Date:** 2015/07/16

**Note:**

None

**Problems Resolved:**

- **Fixed Security vulnerability**
  - UPnP Buffer Overflow - reported by Samuel Huntley - [samhuntley84@gmail.com](mailto:samhuntley84@gmail.com)
  - HTTP Buffer Overflow - reported by Samuel Huntley - [samhuntley84@gmail.com](mailto:samhuntley84@gmail.com)

**Enhancements:**

None

**Known Issues:**

None

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.